

The water rushed through two levels and finally into the basements. Operating, imaging, offices, physical therapy, laboratories, waiting rooms, common areas, document storage, and visiting rooms were all impacted.

Signal arrived within 30 minutes of receiving the call. Signal worked with Beaumont and their property manager, The Farbman Group, to dewater, dehumidify and mitigate this water loss.



## The scope of the recovery work included:

- Dewatering
- Humidification control
- Environmental desiccant drying
- Photo-documenting & content inventory
- Non-salvage inventory and removal
- Valuation appraisals & demolition
- Mechanical room restoration
- Duct cleaning & large electrical panel repairs
- Asset restoration & Equipment drying